

Basic Electrostatics System

ES-9080A





Table of Contents

Equipment List.....	3
Introduction.....	4
Equipment Description	5 - 10
Electrometer	5
Electrostatics Voltage Source	6
Variable Capacitor	7
Charge Producers and Proof Plane.....	7
Faraday Ice Pail.....	9
Conductive Spheres.....	10
Conductive Shapes.....	10
Electrometer Operation and Setup Requirements	11
Suggested Demonstrations	13 - 34
Demonstration 1: Faraday Ice Pail and Charge Production.....	13 - 16
Demonstration 2: Charge Distribution.....	17 - 20
Demonstration 3: Capacitance and Dielectrics	21 - 30
Demonstration 4: Charging and Discharging Capacitors	31 - 34
Technical Support, Copyright and Warranty Information	35
Product End of Life Disposal Instructions.....	36

Basic Electrostatics System

ES-9080A

Equipment List



Included Equipment	Model Number*
1. Basic Electrometer (cables not shown)	ES-9078A
2. Electrostatics Voltage Source (cable and AC adapter not shown)	ES-9077
3. Basic Variable Capacitor (cable not shown)	ES-9079
4. Faraday Ice Pail and Shield	ES-9042A
5. Charge Producers (2) and Proof Plane (1)	ES-9075B
6. Conductive Spheres (2)	ES-9059B
7. Conductive Shapes (2)	ES-9061

*Use Model Numbers to expedite replacement orders.

Additional Equipment	
PASCO data acquisition Interface and software	See PASCO catalog
Charge, Equipotential, and Field Mapper	ES-9060

Introduction

Demonstrations of electrostatic phenomenon have traditionally been limited to the simplest experiments, using the most elementary equipment, because of problems with technique and apparatus. Moreover, the traditional demonstrations usually gave qualitative rather than quantitative results. PASCO has attempted to remedy this by designing the complete ES-9080A Basic Electrostatics system. This guide will give the instructor enough of a step-by-step explanation to master demonstration techniques. The range of demonstrations in this guide more than covers the material usually presented in an undergraduate unit on electrostatics.

Keep in mind the following principles for your electrostatic demonstrations:

- Read the “Equipment Description” of this manual, which provides information about using the equipment.

Equipment orientations - Arrange the apparatus to be used so that it is sufficiently separated and neatly arranged to insure that the students can clearly see the setup. Each demonstration includes a diagram of the suggested equipment setup. A preferred setup would also use a computer with a *PASCO*® interface to display the readings from the Electrometer (ES-9078) in a computer screen that all can easily see. (You can use an analog display, for example, to show the deflections of the needle, or a digits display to show the voltage.) If a computer is not available, set the basic electrometer upright to allow the meter to easily be seen. Always consider how the equipment arrangement may affect charge distributions. For example, a misplaced power supply can easily change the charge distribution on a nearby sphere. Finally, always stand behind the demonstration table to avoid obstructing anyone’s view.

- Earth grounds - Although it is not always strictly necessary, the demonstrator should be connected to an earth ground. Stray charges on the demonstrator can cripple an experiment. Also, keep the electrometer grounded unless specific instructions are given to the contrary.
- Avoid unnecessary movement - If the demonstrator walks around or waves his/her arms excessively, charge can build up in clothing and affect the results.
- Humidity - The PASCO basic electrometer has been designed to minimize the effects of humidity. However, a particularly humid day can cause charges to leak off any of the apparatus, radically changing the charge distribution. To help minimize leakage, keep all equipment free of dust and oil (e.g. from fingerprints). On the other hand, a particularly dry

day can cause charge to easily build up in any moving object, including people. Minimize all movement when demonstrating on a very dry day.

- Practice - Nothing can ruin the instructive value of a demonstration more than failure due to a demonstrator's unfamiliarity with the equipment and procedure.

Before presenting a series of electrostatic demonstrations, the student (and of course, the instructor) should be made aware of the following:

- The theory and use of the Faraday Ice Pail. (This is adequately covered in the "Equipment Description" section and in Demonstration 1.)
- The possible distortion of charge density due to improper use of the proof plane. (See the "Equipment Description" section.)
- Residual charge may build up in the plastic insulator between the handle and disk of the proof plane and charge producers. Make sure to ground these parts before any experiment.
- The capacitance of the electrometer must be considered when calculating the magnitude of a charge from the voltage reading of the electrometer. (See Demonstration 3 for the procedure necessary to determine the electrometer's capacitance.)

By following the above principles and by practicing, the demonstrator should have a high degree of success with the demonstrations and find their educational effect of great value.


Equipment Description

Electrometer (ES-9078A)

The Model ES-9078A Electrometer is a voltmeter used for direct measurements of voltage and indirect measurements of current and charge. Because of its high ("infinite") impedance of $10^{14} \Omega$, it is especially suited for measuring charge in electrostatic experiments. It has a sensitivity nearly one thousand times that of a standard gold-leaf electroscope, a center-zero meter that directly indicates charge polarity, and a digits display. The electrometer measures charges as low as 10^{-11} coulombs.

The electrometer includes a signal input cable (shielded), a banana plug patch cord, a signal output (interface) cable, and a grounding cable (for use with the ES-9079 Basic Variable Capacitor).


With these features, you'll find that your electrostatics demonstrations and labs are easier to perform and, with quantitative data, are more informative.



The electrometer is powered by four AA-alkaline batteries (included) that can be replaced by opening the back casing of the electrometer. One of the front panel range-indicator light emitting diodes (LEDs) will blink slowly when the batteries need to be replaced. When replacing batteries, do not touch any of the components or wires on the integrated circuit panel because they are all static sensitive.

Electrostatics Voltage Source (ES-9077)

The ES-9077 is a high voltage, low current power supply designed exclusively for experiments in electrostatics. It has outputs at 30 volts DC for capacitor plate experiments, and 1 kV, 2 kV, and 3 kV outputs for the Faraday ice pail and conductive sphere experiments. All of the voltage outputs (except for the 30 volt output) have a series resistance associated with them which limits the available short-circuit output current to about 8.3 microamps. The 30 volt output is regulated, but is capable of delivering only about 1 milliamp before falling out of regulation. An AC adapter (not shown) is included.



Variable Capacitor (ES-9079)

The PASCO experimental variable capacitor consists of two conductive plates, 20 cm in diameter, which can be adjusted to various separations. The movable plate is mounted on a calibrated slide which gives the plate separation directly in centimeters. Binding posts on each plate are provided for electrical connection. Three plastic spacers are attached to the fixed plate so that when the movable plate is made to touch these spacers, the plate separation is 1 mm.

A low-capacitance cable to connect the plates to the electrometer is included. Keep the leads of the cable separated as much as possible to minimize their capacitance.

It is very important that the plates of the capacitor remain parallel. It is possible that through mishandling, they will cease to be parallel, and adjustments must be made. On the back side of the movable plate are two screws for adjusting the plate horizontally and vertically.




Figure 3: Variable Capacitor

Keep the plate supports clean to prevent charge leakage from the plates.

Charge Producers and Proof Plane (ES-9057B)

The Charge Producers and the Proof Plane are electrostatic components for use with the PASCO Electrostatic System. The charge producers are used to generate charges by contact. The proof plane is used to measure charge density on a charged surface.

The charge producers consist of two wands, one with dark material and one with white material attached to a conductive disk, as shown in Figure 4. If the dark and white surfaces are briskly rubbed together, the white surface acquires a positive charge, and the dark surface acquires a negative charge.




Figure 4: Charge Producers

Here are some guidelines in the proper use and care of the charge producers that are important to remember:

- If a zero charge is desirable, discharge the charge producers by touching the conductive disk to ground. To be sure the disk is fully discharged, gently breathe on the non-conductive neck. The moisture from your breath will help remove any stray charge.

- Avoid touching the neck during normal use. The oils from your hands will provide a path for charges to leak off. If you experience a lot of leakage, wash the white non-conductive neck with soap and water, rinsing generously; the leakage should disappear. Occasionally clean the disk surfaces with alcohol.
- When you first use the charge producers, or just after cleaning, they may not produce charges readily. Rub the white surface vigorously on the conductive proof plane disk.
- The charge producers are designed to be used with the ES-9078 Electrometer. They do not produce sufficient charge for use with a standard electroscope.

The Proof Plane

As shown in Figure 5, the proof plane is an aluminum-covered conductive disk attached to an insulated handle. The conductive disk material is carbon-filled black polycarbonate (about $10^3 \Omega$) with an aluminum surface. The nonconductive neck is white polycarbonate (about $10^{14} \Omega$).

The proof plane can be used to sample the charge density on charged conductive surfaces. A Faraday Ice Pail and Electrometer can then be used to measure the charge density on the proof plane (see Figure 6).

By touching the proof plane to a surface, the proof plane will acquire the same charge distribution as the section of the surface it touched. By measuring the charge on the proof plane, the charge density on that part of the surface can be determined. The greater the charge on the proof plane, the greater the charge density on the surface where the proof plane made contact.

When a proof plane is touched to a conductive surface, the proof plane becomes part of the conductive surface. If the effect on the shape of the surface is significant, the sampling of the charge density will not be accurate. Therefore, always touch the proof plane to the conductor in such a way as to minimize the distortion of the shape of the surface.






Figure 7 shows the recommended method for using the proof plane to sample charge on a conductive sphere.




Use the conductive knob on the end of the proof plane to sample the charge density inside a hollow sphere (such as ES-9061 Conductive Shapes).

Faraday Ice Pail (ES-9042A)

The PASCO Faraday Ice Pail is shown in Figure 8. Originally designed by Michael Faraday, it works on the principle that any charge placed inside a conducting surface will induce an equal charge on the outside of the surface. It is an excellent product for sampling charges and charge distributions. The PASCO version illustrated above consists of two wire mesh cylinders, one inside the other, mounted on a molded plastic bottom.

The outer cylinder is called the shield. It provides complete visibility to the inside of the pail and, when grounded, helps eliminate stray charges and AC fields.

The inner cylinder is the actual pail. The pail is mounted on insulated rods; the pail is 10 cm in diameter and 15 cm high. When a charged object is placed inside the pail, but without touching it, a charge of the same magnitude is induced on the outside of the pail (see Figure 6). An electrometer connected between the pail and the shield will detect a potential difference. The greater the charge, the greater the potential difference. So even though the electrometer will give readings of voltage, it is possible to use those values as relative charge measurements.



To prevent stray charges from producing erroneous results, it is extremely important that the Faraday Ice Pail be momentarily grounded prior to starting any experiment. The demonstrator must also be continually grounded while performing an experiment.

The Charge Producers are used as charged objects to lower into the ice pail. The Proof Plane is used to sample surface charge densities.

Conductive Spheres (ES-9059C)


The conductive spheres are used to store electrical charge. The spheres are 13 centimeters (cm) in diameter and are made of nickel-plated acrylonitrile butadiene styrene (ABS) plastic. Each is mounted on a non-conductive rod of polycarbonate (about 10^{14} ohms) and attached to a stable support base. Each sphere has a thumbscrew terminal on the lower half of the sphere for attaching a ground cable or a lead from a voltage source. The sphere and insulating rods should be kept free of dirt, grease, and fingerprints to minimize charge leakage from the sphere.

Conductive Shapes (ES-9061)

The conductive shapes are special objects upon which to store electrical charges. Both shapes are made of nickel-plated ABS plastic. The Conductive Hollow Sphere is 13 centimeters (cm) in diameter and has a 3.8 cm (1.5 inch) diameter hole at the top that allows access to the inside of the sphere. The Conductive Conical Shape is spherical on one side and tapers to a bulbous shape on the other side. Each is mounted on a non-conductive rod of polycarbonate (about 10^{14} ohms) and attached to a stable support base. Each shape has a thumbscrew terminal on the lower half of the shape for attaching a ground cable or a lead from a voltage source.

The Conductive Hollow Sphere allows you to measure the amount of charge on the *inside* of a charged conductive sphere.

The Conductive Conical Shape allows you to measure the difference in charge density from one end to the other of the shape and compare the distribution of charge density to that of a charged conductive sphere.



NOTE: When handling the conductive shapes, take care to keep each shape and non-conductive rod free of dirt, grease, and fingerprints to minimize leakage of charge from the shapes.

Five binding posts allow the voltage source and/or the electrometer to be connected to components.

NOTE: The proof planes can be used to test for charge polarity on conductors of any shape. However, for accurate readings of charge density, the conductor surface sampled has to be considerably larger than the disk of the proof plane and have a relatively large radius of curvature at the point of contact.

Electrometer Operation and Setup Requirements

The controls on the front panel of the electrometer are explained in Figure 1. Whether you are using the electrometer to measure voltage, current or charge, the setup procedure should be followed each time you turn on the electrometer.



Warning:

To avoid electrical shock and/or injury, observe the following safety precautions:

1. Never use the electrometer for measuring potentials more than 100 volts.
2. Never connect the electrometer to an electrostatic generator, such as a Van de Graff generator or a Wimshurst machine.
3. Never touch the signal input leads until you have grounded yourself to an earth ground. A person walking across a rug on a cool, dry day can easily acquire a potential of several thousand volts.

Setup

1. Connect the signal input test lead to the signal input BNC connector of the electrometer.
2. Connect the ground post of the electrometer to an earth ground.
3. Push the power button ON. One of the range switch LEDs will blink twice in quick succession.
4. Press the ZERO button to zero the meter. The LED in the meter display will align with “0” and the digits display will read “0.0”. You’re now ready to use the electrometer to measure charge, current or voltage.

5. Use the push button to set the voltage to the desired range. The range setting refers to the voltage input required to produce a full-scale meter deflection (e.g., a setting of 30 means that a full-scale meter deflection indicates a voltage of 30 volts).

Important Points for General Operation:

1. Between measurements, always press the ZERO button to discharge all current from the electrometer.
2. Shorting the test leads together is insufficient. There may still be stray charges within the electrometer circuitry.
3. For good results, it is essential that the electrometer be connected to an earth ground (a water pipe, the ground wire from a 120 VAC socket, or the COM port on the electrostatics voltage source). Only an earth ground provides a sufficient drain for excess charges that may build up during an experiment. It is also helpful if the experimenter is grounded. Just touch one hand to a good earth ground just before, or during measurements.

More information on taking accurate measurements is provided in the demonstrations.

Demonstration 1: Faraday Ice Pail and Charge Production

Equipment Required:	
Electrometer (ES-9078A)	Faraday Ice Pail (ES-9042A)
Charge Producers (ES-9057B)	Signal Input Cable (test leads)
Earth ground connection	Proof plane (optional)

Suggestions for Introducing the Experiment

Start by showing that the electrometer is directly measuring potential difference by connecting a battery to it and measuring its voltage. You can explain that when using the ice pail, you will be only indirectly measuring charge, knowing that the amount of charge is proportional to the voltage. The readings will be in volts, not in coulombs. Change the polarity of the leads to show how the meter light emitting diode (LED) deflects in the opposite direction. Explain how this can tell us the type of charge in the ice pail.

Equipment Setup




Figure 1.1: Demonstration Setup


Introduction

The purpose of this demonstration is to investigate the relation between the charge induced on the ice pail by a charged object placed in the pail, and the charge of the object. This demonstration is also useful for investigating the nature of charging an object by contact as compared to charging it by induction, and to demonstrate the conservation of charge.

Before beginning any experiment using the ice pail, the pail must be momentarily grounded. When the ice pail is connected to the electrometer, and the electrometer is connected to an earth-ground, simply press the ZERO button whenever you need to discharge both the pail and the electrometer. While conducting an experiment, it is convenient to keep yourself grounded, by continuously resting one hand on the upper edge of the shield, or by direct contact with the earth-ground connector.



WARNING: Make sure the electrometer is connected to an earth ground, or the pail will not be properly grounded. Performing tests or experiments with an ungrounded pail could cause possible electrical shock or injury.



Procedure 1A: Charging by Induction vs. Charging by Contact

1. Connect the electrometer to the Faraday Ice Pail as shown in Figure 1.1. Make sure to ground the electrometer and the ice pail. The electrometer should read zero when grounded, indicating there is no charge in the ice pail. Press the ZERO button to completely remove all charge from the electrometer and the ice pail.
2. Always start with the voltage range in the higher setting (100 V) and adjust down if needed. Analog meters are typically most accurate in the range of 1/3 to 2/3 of full scale.
3. The charge producers will be used as charged objects. Here is a general procedure to follow when charging the producers:
 - Always remove any stray charge on the necks and handles of the charge producers by touching the necks and handles to the grounded shield. You must also be grounded while doing this. It also helps if you breathe on the neck of the charge producer, so that the moisture in your breath removes any residual charge on the neck.
 - Rub the white and blue surfaces together to separate charges.
 - Keep in your hand only the producer you are going to use. Put the other charge producer away, far from contact with any of the ice pail surfaces.

- Before inserting the charged disk in the ice pail, make sure you're touching the grounded shield.
4. Carefully insert the charged object into the ice pail, all the way to the lower half of the pail, but without letting it touch the pail. Note the electrometer reading.
 5. Remove the object and again note the electrometer reading. If the handle never touched the pail, the reading must be zero.

Question: Why was there a potential difference between the pail and the shield only while the charged object was inside?

6. Push the ZERO button to remove any residual charge. Now insert the object again, but let it touch the ice pail. Make sure your students know and see that you are touching the ice pail with the charged disk this time.
7. Remove the object and note the electrometer reading.

Questions: Why is there now a permanent potential difference between the ice pail and the shield? Where did the charge on the ice pail come from?

8. To show that the charge gained by the ice pail was lost by the disk, ground the ice pail to remove all charge. Press the ZERO button to remove residual charges from the electrometer. Insert the charge producer again into the ice pail. Does any charge remain on it?

Procedure 1B: Conservation of Charge

1. Starting with initially uncharged charge producers, rub the blue and white materials together. Follow the general procedure for charging listed in part 1A, except that in this case you must keep both producers from touching anything else after charging. (Keep them in your hands, without letting them touch each other or the ice pail.)
2. Use the Faraday Ice Pail to measure the magnitude and polarity of each of the charge producers by inserting them one at a time into the ice pail and noting the reading on the electrometer.

Questions:

What is the relation between the magnitude of the charges?

What is the relation between the polarity of the charges?

Was charge conserved in the demonstration?

3. Completely remove all charge from the charge producers by grounding them. Do not forget to also remove any stray charge from the necks and handles.
4. Insert both charge producers into the ice pail and rub them together inside the pail. Note the electrometer reading. Do not let the charge producers touch the pail.

5. Remove one charge producer and note the electrometer reading. Replace the charge producer and remove the other. Note the electrometer readings. Using the magnitude and polarity of the measurements, comment on conservation of charge.

Extra Things to Try

1. Try repeating Procedure 1A with the opposite charged wand.
2. Try rubbing the white charge producer with a proof plane, then measure the magnitude and polarity of the charges produced.
3. Try rubbing the blue material with a proof plane. Measure the magnitude and polarity of the charges produced.
4. Construct a list of materials such that if a material lower in the list is rubbed with a material higher in the list, the higher material is always positive.

Demonstration 2: Charge Distribution

Equipment Required:	
Electrometer (ES-9078A)	Faraday Ice Pail (ES-9042A)
Electrostatic Voltage Source (ES-9077)	Proof Plane
Conductive Spheres, 13 cm (ES-9059B) (2)	Signal Input cable (Test leads)
Earth ground connection (patch cord)	Conductive Shapes (ES-9061)

Equipment Setup




Figure 2.1 Demonstration Setup

Introduction

The purpose of this demonstration is to investigate the way charge is distributed over a surface by measuring variations of charge density. A charged surface will be sampled with a proof plane. The proof plane will then be inserted in the Faraday Ice Pail to measure the charge. By sampling different sections of the surface, the relative charge density can be observed. For example, you may find that the amount of charge on two equal sized regions on the surface of a conductor may differ in magnitude or even in sign. This occurs for non-uniform charge distribution. Alternately, you may observe that everywhere on the surface the charge has the same magnitude and sign. This occurs for uniform charge distribution.

An important aspect of measuring charge distributions is charge conservation. The proof plane removes some charge from the surface it samples. If the proof plane is grounded after each measurement, the surface will be depleted of charge with consecutive measurements.

However, by not grounding the proof plane (and by not letting it touch the ice pail), the charge on the surface is not depleted. That charge which the proof plane removed for one measurement is always returned to the surface when the next sampling is made.

NOTE: When the disk of the proof plane touches the surface being sampled, it essentially becomes part of the surface. To minimize distortion of the surface shape when sampling, hold the proof plane flat against the surface, as indicated in the accessory instructions. Please refer to the accessory instructions for details on how to use the proof planes.

Procedure:

1. Before starting, make sure the Faraday Ice Pail is properly grounded, with the shield connected to earth ground. The electrometer, connected to the pail, must also be grounded (for example, when connected to the COM port on the electrostatics voltage source). Follow the setup in Figure 2.1, with the black lead connected over the edge of the shield and the red lead connected over the edge of the ice pail.
2. Place the two conductive spheres at least 50 cm apart. Connect one of the spheres to the +2000 VDC port on the Electrostatic Voltage Source (ES-9077). The voltage source should be grounded to the same earth ground as the shield and the electrometer. (An earth ground for the system is the AC adapter power supply for the Electrostatic Voltage Source.) The connected sphere will be used as a charged body.
3. Momentarily ground the other sphere to remove any residual charge from it.
4. Start the demonstration by sampling and recording the charge at several different points on the sampling sphere (the sphere that was grounded in step 2). Choose points on all sides to represent an overall sample of the surface.
5. Now bring the +2000 VDC charged sphere close to the grounded sphere, until their surfaces are about 1 cm apart. Turn the voltage source ON, then sample and record the charge at the same points sampled before.
6. Momentarily ground the sampling sphere again, by touching one hand to the grounded ice pail shield and the other hand to the sphere. (Make sure the ice pail is grounded before doing this.) Again, sample and record the charge at the same points sampled before.
7. Remove the +2000 VDC charged sphere until it is at least 50 cm away from the sampling sphere. Again, sample and record the charge at the same points sampled before.

Analysis


1. What produced the charge distributions at each step of the experiment?
2. Why did any charge remain on the second sphere even after it was grounded?

Conductive Conical Shape

1. Remove the two conducting spheres. Connect the conductive conical shape to the +2000 VDC port on the Electrostatics Voltage Source.
2. Use the proof plane to sample charge at the larger rounded end and then at the narrow end.

Analysis

1. Which end of the conical shape has the higher charge density?
2. Why?



Conductive Hollow Sphere


1. Remove the conducting conical shape. Connect the conductive hollow sphere to the +2000 VDC port on the Electrostatics Voltage Source.
2. Use the proof plane to sample the charge on the outside surface of the sphere. Then use the conductive knob end of the proof plane to sample the charge inside the sphere.

Analysis

1. How do the charges compare between the outside of the hollow sphere and the inside of the hollow sphere?

Extra Things to Try

1. To show that the charge on a conductor always resides on the outside surface, bend a flexible sheet of metal into a cylinder. Charge the cylinder and measure the charge density in the inner and outer surfaces. Notice that charge is always on the outside.
2. To show how the surface shape affects charge density, try touching two charged proof planes together so that they are symmetrical around their point of contact. Measure the charge on each. Next touch them in an asymmetrical manner and measure the charge in each. Does one have more charge than the other? Which one? (Be sure to eliminate stray charges from necks and handles, to prevent erroneous readings.)



Demonstration 3: Capacitance and Dielectrics

Equipment Required:	
Electrometer (ES-9078A)	Faraday Ice Pail (ES-9042A)I
Charge Producers (ES-9057B)	Proof Planes (ES-9057B)
Electrostatic Voltage Source (ES-9077)	Signal Input cable (Test leads)
13 cm Conductive Spheres (2) (ES-9059B)	Variable Capacitor (ES-9042A)
Capacitor (about 30 pF) (ES-9043)	Sheet of dielectric material (See Table 3.1 for options)


Introduction

The purpose of this series of demonstrations is to investigate the relationship between charge, voltage and capacitance for a parallel plate capacitor. Each one of the variables will be held constant in turn, varying one of the others while measuring the third. The capacitance of a parallel plate capacitor is given by $C = \frac{\epsilon A}{d}$, where ϵ is the dielectric coefficient, A is the plate area, and d is the plate separation. Various materials can be inserted between the plates to measure the dielectric coefficient of the materials.

NOTE: At this point, the students should understand the theory of capacitors connected in parallel. If not, go to Procedure D of this demonstration.

For all experiments, the electrometer can be thought of as an infinite impedance voltmeter in parallel with a capacitor, as shown in Figure 3.1. The capacitor C_E represents the internal capacitance of the electrometer, plus the capacitance of the leads.

Whenever you want quantitative measurements of charge, voltage or capacitance, you need to consider the effect of the internal capacitance of the electrometer, unless you are certain that the capacitor you are using has a high enough capacitance to disregard C_E . This is not true, however, when using the Basic Variable Capacitor (ES-9079).



Procedure 3A: Measuring the Electrometer's Capacitance

Use this procedure to measure a precise value of the capacitance provided by the electrometer and all cables connected to it. If you are interested in qualitative, rather than quantitative experiments, this procedure is not necessary.

When a capacitor of known capacitance C is charged by a known voltage V , the charge in it is given by $Q=CV$.

If the known charged capacitor is connected across the leads of the electrometer, it is connected in parallel with the internal capacitance of the electrometer, C_E . The total capacitance becomes $C + C_E$.

The known capacitor will discharge across the electrometer and a voltage, V_E , will be read. Since the total charge in the system is still just the charge of the known capacitor, we know that $CV=(C + C_E)V_E$.

1. Obtain a low leakage (polypropylene, or air dielectric) capacitor of known value, C , around 30 picofarads (pF).
2. Charge the capacitor with a known voltage V , not higher than 100 V (the limit of the electrometer).
3. Remove the charged capacitor from the power supply used to charge it, being careful not to ground it in any way, to avoid removing the charge.
4. Connect the charged capacitor across the electrometer input leads. Note the voltage V_E indicated by the electrometer.
5. Calculate the internal capacitance of the electrometer.

$$C_E = \frac{(V - V_E)}{V} C$$


Procedure 3B: Measuring C , V and Q for a Parallel Plate Capacitor

The purpose of the experiments listed in this part is to qualitatively study the relationship between C , V , and Q for the parallel plate capacitor. Values read by the electrometer are to be used as relative, comparative measurements. The electrometer can be connected to a computer and used with a *PASCO*[®] interface to obtain a graphical display of information.

3B.1: V Measured, Q Variable, C Constant

1. Figure 3.2 below shows the equipment set up. The Basic Variable Capacitor is connected to the electrometer. The electrometer is grounded to earth (such as the COM port on the electrostatic voltage source). One of the spheres is connected to the +2000 VDC port on the

voltage source. Take care to place the capacitor sufficiently far away from the sphere and the voltage source, to prevent it from being charged by induction.




2. Press the **ZERO** button to remove any residual charge from the electrometer and the plates of the capacitor.
3. Set the plate separation to about 2 mm. Use a proof plane to transfer charge from the charged sphere to the capacitor plates. The charge is transferred merely by touching the proof plane to the sphere and then to one capacitor plate. If you always touch the sphere and the capacitor plate at the same place, equal amounts of charge will be transferred each time.

Question: Why is it sufficient to touch only one plate of the capacitor?

4. Observe how the potential difference reading from the electrometer varies as more charge is put in the capacitor.

5. Double the plate separation to 4 mm and repeat the procedure. What happens to the potential now? Compare the values to the previous case.




3B.2: Q Measured, C Variable, V Constant

1. Figure 3.3a above shows the equipment set up. The Basic Variable Capacitor has an initial plate separation of 6 cm and is connected to the +2000 VDC port on the voltage source. The Faraday Ice Pail is connected to the electrometer, and the electrometer is grounded to earth ground (i.e., through the COM port on the electrostatics voltage source).
2. Momentarily ground a proof plane and then use it to examine the charge density of the capacitor, using the ice pail to measure the charge. Investigate the charge density at various points on the plates — both on the inner and the outer surfaces. How does the charge density vary over the plate?
3. Choose a point near the center of one capacitor plate and measure charge density in this area at different plate separations. (Keep in mind whether you are increasing or decreasing the capacitance by moving the plates.) How does the charge vary with capacitance?

3B.3 Q Measured, V Variable, C Constant

1. Figure 3.3b shows the equipment set up, which is identical to the setup for B2. The Variable Capacitor has an initial plate separation of 6 cm and is connected initially to the +3000 VDC

port on the voltage source. The Faraday Ice Pail is connected to the electrometer and the electrometer is grounded to earth (i.e., through the COM port on the voltage source.).



- Keep the plate separation constant and change the potential across the plates by changing the setting of the voltage source. You have to move the connecting cable from the +3000 V to the +2000 V port. Examine the charge density near the center of one capacitor plate. How does the charge vary with the voltage? Repeat with +1000 VDC.

3B.4: V Measured, C Variable, Q Constant

1. Figure 3.4 shows the equipment set up. The Variable Capacitor is connected to the electrometer and the electrometer is grounded to earth (through the COM port on the voltage source). The voltage source will be used to only momentarily charge the capacitor.




Figure 3.4: Demonstration Setup

2. With the plate separation at 2 mm, charge the plates by momentarily connecting them across the voltage source, set at 30 V. Adjust the scale sensitivity of the electrometer so that the initially charged plates represent a meter reading of about 1/5 scale.
3. Increase the plate separation and note the electrometer's readings at various separations. How does the potential vary with capacitance?

NOTE: An alternative method is to charge one of the spheres and then transfer some charge to the capacitor. The charge, however, will not be as high.

Procedure 3C: Dielectric Coefficients

The dielectric coefficient κ is the dimensionless factor by which the capacitance increases (relative to the value of capacitance before the dielectric) when a dielectric is inserted between the plates. It is a fundamental property of the dielectric material and is independent of the size or shape of the capacitor. Table 3.1 lists the dielectric coefficients of some common materials.

The ideal procedure to measure κ would be to simply slip a piece of dielectric material between a set of charged capacitor plates and then note the changes in potential. However, sliding a dielectric between the plates of the capacitor when they are too close together can generate a significant static charge that will alter the measurements. Hence, it is best to proceed as follows:

NOTE: Depending on the model of parallel plate capacitor you have, there may be only one plate that is movable. If your model allows both plates to be moved, choose one to keep fixed and the other to be the movable one.

1. Connect the electrometer across the plates of the capacitor and set the separation between the plates to about 3 mm.
2. Raise the side of the set up nearest the movable plate by setting a block about 3 cm high below it, as shown in Figure 3.5.





Figure 3.5: Demonstration Setup

3. Use the voltage source to momentarily touch the plates and charge them to about 4/5 full scale. Record the voltage reading of the electrometer, V_i .
4. Carefully increase the separation of the plates until it is enough to insert the dielectric without forcing it. It should be enough so that you can simply lean the dielectric sheet against the stationary plate. Make sure the dielectric you are using is free of residual charge before inserting it.

5. After inserting the dielectric, return the plates to the original 3 mm separation and record the new electrometer reading, V_f .
6. Pull the plates apart again, and lift and carefully remove the dielectric sheet.
7. Return the plates to the original 3 mm separation and check that the electrometer reading agrees with the original V_i reading.

Analysis:

The calculations needed to determine the dielectric constant are long, but straight forward:



Before inserting the dielectric...

Let q_p be the charge on the capacitor plates, and C_p be the capacitance of the plates, without the dielectric.

Let q_E be the charge on C_E , the internal capacitance of the electrometer.

Let V_i be the initial reading of the electrometer.

The total charge in this initial system is given by $q_p + q_E = (C_p + C_E)V_i$

After inserting the dielectric...

Let q'_p be the new charge on the capacitor plates; the capacitance is now C'_p .

Let q'_E be the new charge on C_E , the internal capacitance of the electrometer. Since there is no dielectric in C_E , its value is still the same.

Let V_f be the new reading of the electrometer.

The total charge in the system after inserting the dielectric is given by

$$q'_p + q'_E = (C'_p + C_E)V_f$$

Now, the total amount of charge in the system was never changed, so

$$q_p + q_E = q'_p + q'_E$$

and $(C_p + C_E)V_i = (C'_p + C_E)V_f$.

After some algebra and rearranging, you find that

$$\frac{C'_p}{C_p} = \frac{C_E(V_i - V_f) + C_p V_i}{C_p V_f}$$

where the ratio C'_p/C_p is the dielectric coefficient κ :


$$\kappa = \frac{\epsilon A_d}{\epsilon_0 A_d} = \frac{C'_p}{C_p}$$

Table 3.1: Some Dielectric Coefficients

Material	κ
Vacuum	1
Air	1.00059
Polystyrene	2.6
Paper	3.7
Pyrex	4.7
Mica	5.4
Porcelain	6.5

Procedure 3D: Capacitors in Series and in Parallel

The purpose of this demonstration is to examine the effect of placing capacitors in series and in parallel. You will need two capacitors of known value (between 200 - 400 μF , to ignore the internal capacitance of the electrometer), a DC voltage source, the electrometer, some cables, and a double throw switch.



3D.1: Capacitors in Series

Make sure all capacitors are uncharged before connecting them. (Use a short wire to momentarily short each one.)

1. Set up the series circuit, as shown in Figure 3.7a.
2. Plug in to the 30 VDC output on the Voltage Source. Close switch A to charge capacitor C_1 .
3. Using the known value of C_1 , calculate the initial amount of charge on C_1 . Let's call it Q_0 . (Remember $Q = CV$.)
4. Throw the switch to position B. C_1 and C_2 are now in series.
5. Use the electrometer to measure the voltage drop across each of the capacitors (V_1 and V_2).
6. Using the known values of capacitance, determine the amount of charge in each of them. (Q_1 and Q_2).
7. Questions: Can you find a relation between V_1 , V_2 and the voltage of the source? How does Q_1 and Q_2 relate to the original charge on C_1 ?

3D.2: Capacitors in Parallel

1. Make sure all capacitors are uncharged before connecting them to the circuit.
2. Set up the parallel circuit, as shown in Figure 3.7b.
3. Set the voltage source to 30 VDC. Close the switch to charge the capacitors.
4. Use the electrometer to measure the potential difference across each of the capacitors. How does it compare to the voltage of the source?
5. Use the known value of the capacitances to determine the charge in each capacitor. How are the charges related?

Analysis:

1. Compare series and parallel capacitors in terms of charges, voltages and capacitance.

Demonstration 4: Charging and Discharging Capacitors

Equipment Required:	
Electrometer (ES-9078A)	Faraday Ice Pail (ES-9042A)
Power Amplifier (CI-6552A)	Signal Input cable (Test leads)
Capacitors, 200-400 μF	Resistors, (10-90 $\text{k}\Omega$; 10-1000 Ω)
Computer with <i>PASCO</i> interface	DataStudio® software

Introduction

The purpose of this demonstration is to investigate how the voltages across a capacitor and a resistor vary as the capacitor charges and discharges, and to find the capacitive time constant. When a capacitor is connected to a DC power supply, charge builds up in the capacitor and the potential difference across the capacitor increases until it equals the voltage of the source. Both the charging and the discharging of a capacitor are characterized by a quantity called the time constant, which is the product of the capacitance, C and the resistance R . That is,

$$\tau = RC.$$

Use capacitor values in the recommended range, so that the internal capacitance of the electrometer needs not be considered. You can adjust the resistance value for a convenient RC constant.


There are two variations of the same activity presented here. The first uses a direct DC voltage source and results are obtained in a voltage vs. time graph. Use higher resistances (10-90 $\text{k}\Omega$ for this method. The second uses a signal generator with a square wave to charge and discharge the capacitor. Use lower resistances (100-1000 Ω for this method.

Equipment Setup

The signal output cable of the electrometer allows it to be connected to a *PASCO* interface as an analog sensor.

1. Open the software program and select the electrometer from the list of sensors.

- Set up the circuit shown in Figure 4.1, where the resistor and the capacitor are connected in series to the voltage source, set at 30 VDC. The electrometer output goes to one of the analog channels of the *PASCO* interface . Use a single-pole double-throw switch.



- Set up your experiment display in the computer to plot voltage vs. time. (Refer to the steps listed above for correcting the electrometer readings.)
- With the switch open, press start to begin collecting data. Throw the switch to position A to begin charging the capacitor. Observe the behavior of the voltage on the screen.
- When the charge in the capacitor has reached the value of the source (30 VDC), flip the switch to position B to begin discharging the capacitor. Observe the behavior of the voltage in the screen.
- You may want to try the experiment with different values of R and notice the differences in charging time.

Analysis:

When a capacitor is charged through a resistor from a DC power supply, the charge on the capacitor and the voltage across the capacitor increase with time. The voltage, V , as a function of time is given by

$$V = V_0 (1 - e^{-t/RC}) \text{ where } V_0 \text{ is the charging voltage.}$$

After a time $t = RC$ (one time constant), the voltage across the capacitor has increased to 63% its maximum value ($V = 0.63V_0$ at $t = RC$).


- Calculate 63% of the voltage of the source. Locate the position in the graph where the voltage has reached this value. How long a time has passed to reach 63% of the voltage of the source? This time is RC . (Using the Smart Tool in DataStudio makes these measurements easy!)
- Compare the measured time constant from the graph with the calculated from the known values of C and R . Now, when a fully charged capacitor is discharged through a resistor,

the voltage across (and the charge on) the capacitor decreases with time according to the equation $V = V_0 e^{-t/RC}$. After a time $t = RC$ (one time constant), the voltage across the capacitor decreases to 37% its maximum value.


- Determine how much is 37% of the total voltage and locate where in the discharging plot this value has been reached. How long a time since the start of discharging did it take to reach this value? (Use the smart cursor tools!)
- Compare this measured RC constant with the known value.

Procedure 4B: Charging/Discharging Capacitors with Signal Generator

When a positive square wave signal is applied to a capacitor in an RC circuit, the capacitor periodically charges and discharges, as shown in Figure 4.2. The period of a full charge-discharge equals the period of the wave.



Note: The procedure listed here specifies values for R , C and the frequency of the signal that work well together. If you decide to use any other R or C value, you have to adjust the frequency of the wave. Notice that the voltage has to remain constant for enough time to fully charge the capacitor before the voltage goes to zero and the capacitor is discharged. A good estimate of the time needed to fully charge a capacitor can be determined as $t = RC[\ln V_0 - \ln 0.01]$, where V_0 is the voltage of the source. Choose a signal such that the period of the wave is at least double this charging time.



Experimental Setup

- Set up the circuit shown in Figure 4.3, where the resistor and the capacitor are connected in series to the signal output generator of the *PASCO 750* Interface. Use a $200\ \mu\text{F}$ capacitor and

a resistance of $1000\ \Omega$. The electrometer is reading the voltage across the capacitor, and it is also connected to one of the analog channels of the *PASCO* interface.

2. With the DataStudio software, create a display of voltage vs. time for the readings of the electrometer.
3. Set the signal generator to produce a positive square wave of maximum around 4 volts and of frequency 0.45 Hz. Set the signal generator to AUTO. In this way, the signal will turn on and off as you press Start or Stop to collect data.
4. Start recording data. Observe the behavior of the voltage across the capacitor on the screen. When several cycles of charging-discharging have completed, stop the collection of data.
5. Only one full cycle is necessary to complete all the analysis. Zoom in to a full cycle of charge-discharge.

Analysis:

The analysis is similar to the analysis for Procedure A.

Extra Things to Try:

1. Check what is happening to the voltage across the resistor while the capacitor charges and discharges.

Appendix A: Copyright and Warranty Information

Copyright Notice

The PASCO scientific 012-07227G *Basic Electrostatics System Manual* is copyrighted and all rights reserved. However, permission is granted to non-profit educational institutions for reproduction of any part of the 012-07227G *Basic Electrostatics System Manual*, providing the reproductions are used only for their laboratories and are not sold for profit. Reproduction under any other circumstances, without the written consent of PASCO scientific, is prohibited.

Limited Warranty

PASCO scientific warrants the product to be free from defects in materials and workmanship for a period of one year from the date of shipment to the customer. PASCO will repair or replace, at its option, any part of the product which is deemed to be defective in material or workmanship. The warranty does not cover damage to the product caused by abuse or improper use. Determination of whether a product failure is the result of a manufacturing defect or improper use by the customer shall be made solely by PASCO scientific. Responsibility for the return of equipment for warranty repair belongs to the customer. Equipment must be properly packed to prevent damage and shipped postage or freight prepaid. (Damage caused by improper packing of the equipment for return shipment will not be covered by the warranty.) Shipping costs for returning the equipment after repair will be paid by PASCO scientific.

Credits:

Author: Cecilia Hernandez

Appendix B: Technical Support

For assistance with the Basic Electrostatics Systems equipment or any other PASCO products, contact PASCO as follows:

Address: PASCO scientific

10101 Foothills Blvd.

Roseville, CA 95747-7100

Phone: (916) 786-3800

FAX: (916) 786-3292

Web: www.pasco.com

Email: techsupp@pasco.com

Product End of Life Disposal Instructions:

This electronic product is subject to disposal and recycling regulations that vary by country and region. It is your responsibility to recycle your electronic equipment per your local environmental laws and regulations to ensure that it will be recycled in a manner that protects human health and the environment. To find out where you can drop off your waste equipment for recycling, please contact your local waste recycle/disposal service, or the place where you purchased the product.



The European Union WEEE (Waste Electronic and Electrical Equipment) symbol and on the product or its packaging indicates that this product **must not** be disposed of in a standard waste container.